

Mid-Size Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A111087

Station #: 71805

Station Name: Torque & Throttle 44 Mechanics

Technician #: 84131

Technician Name: Christopher Geveart

Signing Officer #: 90491

Signing Officer Name: Janell Ching

Customer Details:

Name: RITCHIE BROS AUCTION

Address: Box 10, Rouleau, Saskatchewan, S0G 4H0

Inspection Completed Date: 09Aug2024

Inspection Expiry Date: 31Aug2025

Vehicle Details:

VIN: 1GT12REY0KF257032

Odometer Reading: 266014 km

Year: 2019

Vehicle Make/Model: GMC/SIERRA 2500 HD

Plate: CDC3941

Jurisdiction: Alberta

Unit: 100087

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Mid-Size Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71805

Station Name: Torque & Throttle 44 Mechanics

Technician #: 84131

Technician Name: Christopher Geveart

Signing Officer #: 90491

Signing Officer Name: Janeil Ching

Customer Details:

Name: RITCHIE BROS AUCTION

Address: Box 10, Rouleau, Saskatchewan, S0G 4H0

Vehicle Details:

VIN: 1GT12REY0KF257032

Odometer Reading: 266014 km

Year: 2019

Vehicle Make/Model: GMC SIERRA 2500 HD

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
×				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
х				Horn Operation (5)	
x				Mirrors (8)	
×				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
×				Windshield/Other Glass (8)	
×				Gear Position Indicator & Neutral Switch (1)	
х				Instrument Lamps (6)	
×				Accessibility Features/Equip (5)	
х				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
X				Emergency Exits (8)	
×				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
×				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
х				Clutch/Clutch Pedal (1)	

х	Fire Extinguisher/Hazard Kit (5)	
x	Seats/Seat Belts/SRS (8)	
x	Steering Column/Components (4)	
x	Auxiliary Controls/Equip (5)	, , ,
x	Speedometer/Odorneter (5)	
х	Sleering Lash/Travel (5)	
x	Accelerator Pedal/Actuator (1)	
x	Engine Shut Down Control (1)	
x	Engine Start Feature (1)	
x	Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	REPAIRED
×				Headlamp Aim (6)	
×				Reflex Reflectors (6)	
х				Retro Reflective Markings (6)	
×				Body/Bumpers (8)	
х				Trailer Hitch (10)	
×				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
×				Cargo Bodies/Vessels (8)	
×				Sun Visor Exterior (8)	
×				Mud Flaps/Fenders (8)	
×				Trailer Power Cord (7)	
×				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
×				Hybrid Vehicle Drive Systems (1)	
×				Unitized Body Etements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
×				Cab/Hood Safety Catches (8)	
×				Power Steering System (4)	
х				Fuel System (1)	
x			_	Battery/Wiring Condition (7)	
×				Air Suspended Cab (8)	
x				Cab Mounts (8)	
×				Drive Bells (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
		×		Hyd Brake System/Components (3.1)	REPAIRED

x	Air Brake System/Components (3.2)
х	Wheel Bearings (9)
х	King Pins/Ball Joints (4)
x	Steering Linkage (4)
х	Tires/Wheels (9)
×	Self-Steering Axle (4)
х	Engine/Transmission Mounts (1)
x	Frame/Crossmembers/Mounts (8)
х	Suspension/Axles (2)
x	Drive Shaft/Universal Joints (1)
х	Exhaust/Emission System (1)

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off: Tire Tread Depth: 16/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 10 mm • Brake Drum/Rotor: 40.10 mm

Wheel2-Off: Tire Tread Depth: 16/32 in

Brake(1): Disc Brake

Axle 2-Pass

Wheel1-Off: Tire Tread Depth: 16/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 13 mm • Brake Drum/Rotor: 34.25 mm

Wheel2-Off: Tire Tread Depth: 16/32 in

Brake(1): Disc Brake

PASS - vehicle passes inspection Decal # A111087 Inspection Completed Date: 09Aug2024

One or more wheels were removed for inspection. Warning: Wheel nuts MUST be RE-TORQUED within 100-150 km. Failure to do so may result in damage or serious injury.